

Fix: *2 - Wood with through hole studs. Holes 2 mm larger than stud diameter. *3 - Wood with coach screws.

Mark the centre lines of the mounting holes on the flange using a white pencil.

Using the drill bush supplied, drill attachment holes in sealing strip.

Fill the back of the well (the hole) with sand for at least 60 degrees.

Verify that the product is functioning correctly.

Locate the washers and the spring washers over the studs.



- 1 Check : The concrete for firmness, flatness and level. Max. tolerance 2 mm per meter.
- 2 Install the tilting weir in front of the hole and check on overflow being horizontal for the water level.
- 3 Pilot drill all the mounting holes.
- 4 Remove the fitting.

Install the fitting.

right hand sides.

Install the fitting.

Fasten the nuts by hand.

11

12

13

14 15

16

17

18

19 20

21 22

23


40

(**C**)


- 5 Drill the mounting holes through the material
- 6 Clean the fixing holes.
- 7 Apply copper grease to both the nut side of the studs.

Make sure the fixing surfaces are clean and dry.

8 Insert the studs using a hammer drill with attachment fitted.



15-17



- Fit to wood *3
 : Install the product level in front of the opening.

 Pilot drill the mounting holes. Remove the fitting.

 Pre-drill the Ø 7 mm mounting holes.

 See more at points 16 up to and including 21.

 Screw the M10 coach screws in.
- 60 Tube connections ; Th

Tighten the nuts to the correct loading.

- Thermal welding joint.
 - Double socket for an HDPE pipe or a uPVC pipe.

22

Apply sealing strip to the frame flange, first at the bottom across the full width, then with over-lengths (A) on the left and

Apply a generous amount of adhesive to the mating faces (B) of the sealing strip. Press them firmly against the strip.

- Conical tube end for a concrete pipe or a SPIROsol pipe using socket cement.

60

- HDPE flange with flange drilling PN10.



- V Trash screen/Debris trap : Available as an option.